

780 CMR 93.00 Repair, Renovation...of ExistingDwellings

9307.5 Moisture Control and Air Leakage

The deleted text refers to sections not found in the code.

780 CMR 9307.5.4.1 Windows, Skylights...

Exceptions:

1. In the repair of broken...shall require compliance with the applicable requirements of 780 CMR ~~9307.6.3 and 9307.6.4~~ **9307.5.2 and 9307.5.3.**